

DCN Next Generation 4.71 Release Notes



en | Release Notes

DCN Next Generation Release 4.71

Table of Contents

1	This release Contains	2
2	Improved and added Functionality	2
3	Release Compatibility Restrictions	7
4	Software, Firmware & FPGA versions	8
5	Additional Information to the DCN Manuals and Help Files	10
6	Trouble Shootings and known issues	13

1 This release Contains

The following versions are part of this release:

Product	version	Windows 8.1 ^a	Windows 10 ^a
DCN-SW	4.71	Yes	Yes
DCN-SWSMV	4.40	Yes ^b	Yes ^b
DCN-SWSACC	4.40	Yes	Yes
DCN-DLT (for CCU2)	4.70	Yes	Yes
DCN-CCU2	4.70	NA	NA
HdCameraControl	4.70	Yes	Yes
DCN-DLT (for CCU, NCO)	3.10	No	No
DCN-CCU	3.10	NA	NA
DCN-MR	2.30	No	No

Notes:

- home editions of 8.1, or 10 are not supported.
- DCN-SWSMV: exporting voting results to PowerPoint is only supported for PowerPoint 2003.

2 Improved and added Functionality

Release	Release Date	Release Comments
4.71	2020-11-11	New functionality and improvements <ul style="list-style-type: none"> Added Arabic as UI language. Windows 7 is no longer supported.
4.70	2018-08-15	New functionality and improvements <ul style="list-style-type: none"> Added support for Panasonic IP cameras via CGI protocol (HD Integrated Camera Interface Specifications 1.06): AW-HE40, AW-HE50, AW-HE60, AW-HE120, AW-HE130, AW-UE70. Screentext does not function with the Panasonic cameras. Added support for Sony IP cameras via CGI commands for 300/360 series: Sony SRG-300SE/301SE and SRG-360SHE. Screentext does not function with the Sony camera. Improved PIN code behaviour of devices. Fixed DCN-SW Operator client stops functioning when another Operator client disconnects. Fixed HdCameraControl disconnects from Kramer switch after a long time.

Release	Release Date	Release Comments
4.63	2017-11-29	New functionality and improvements <ul style="list-style-type: none"> Improved calibration behaviour of the optical network upon booting and adding and removing devices from the optical network.
4.62	2017-10-13	New functionality and improvements <ul style="list-style-type: none"> Fixed DCN-SW cannot be installed on PC with Windows 10. Microsoft SQL2014 will be installed with new installations. In case of upgrades the existing SQL 2008 will be used.
4.61	2016-9-17	New functionality and improvements <ul style="list-style-type: none"> Fixed Slave CCU resetting issue due to time out, by increasing the time out value.
4.60	2016-7-20	New functionality and improvements <ul style="list-style-type: none"> Fixed DCN-SW server front end application and DCN-SW printing application do not start on French, Portuguese and Spanish Windows. Fixed issues with streaming meeting data in combination with display application and or DCN meeting recorder. Fixed notebook behaviour of devices. Updated CCU2 firmware to support DCN-CCU2 and DCN-CCUB2 hardware version HW01/04. Improved DCN Meeting Recorder in combination with streaming meeting data.
4.50	2015-11-16	New functionality and improvements <ul style="list-style-type: none"> Windows 10 supported. Added Hungarian translations Concentus. Fixed time stamp problem of DCN-MR Remote control via Open Interface for all (Audio) expanders. (Digital IO contacts) Remote configuration via Open Interface of all expanders, AEX, DEX, CIN ,OMI; (Routing of the DCNNG floor and languages to all in- and outputs) Level control for Omneo Media Interface Microphone detection for Interpreter desk (internal, external, auto) via DCN-CCU2 front panel tvONE C2-6204A with 4 HD-SDI inputs is supported in HDCameraControl as successor of the tvONE C2-2355A / S2-108HD combination Removed Webcasting software and manuals from the DVD
4.43	2015-05-15	New functionality and improvements <ul style="list-style-type: none"> Fixed: Notification of disconnection from the Bosch DCN Conference Software. Fixed: Operator application shows error and red cross after setting the Central Control Unit to Standby Changed error message when an ID card reader cannot read ID card into understandable text. Fixed: Discussion unit cannot be controlled from synoptic after a reboot of the CCU. Fixed: Language configuration in DCN-IDESK does not change with meeting after a reboot of the CCU. Improved startup behaviour of Integrus transmitter. Improved Mongolian translations on Concentus. Support of new AD convertor in Integrus Transmitter.

Release	Release Date	Release Comments
4.42	2015-03-18	<p>New functionality and improvements</p> <ul style="list-style-type: none"> • Fixed delay of voting results via SMD if a vote is cast during the start chime • Fixed first vote is not exported via SMD • Fixed card production settings fall back to CRC after opening and closing the card production settings • Fixed error upon closing Configuration Application after producing cards during a running meeting • Fixed DCN-SW does not install on Turkish OS • Fixed focus/control goes to prepared votings when a adhoc voting is started • Fixed problem with Black Magic card (due to new Black Magic drivers) in DCN-SWWA webcasting • Fixed problem with pause behavior of DCN Meeting Recorder
4.41	2014-11-02	<p>New functionality and improvements</p> <ul style="list-style-type: none"> • Improved DCN wireless firmware to make it more robust in environments with a lot of WiFi communication • Unresponsive microphone control in Operator application due to network disconnections • Added DCN-SW icons to DVD
4.40	2014-07-30	<p>New functionality and improvements</p> <ul style="list-style-type: none"> • Added Notebooker configuration to the API and DcnApiDemonstrator • Added AGC on/off to audio outputs of Audio Expander in Individual Channels mode • DCN-CCU2 supports Omneo Media Interface (PRS4OMI4) to interface with DCN multimedia • Added Mongolian to Concentus display • ID cards can be programmed via API with and without CRC • Insert and remove of ID card can be executed via API to enable interfacing with third party identification system • Windows 8.1 support for DCN-SW • Windows 8.1 support for DCN-SWSMV • Windows 8.1 support for DCN-SWSACC • Windows 8.1 support for HdCameraControl • Added Crystal Reports installer to Tools directory (CRRuntime_32bit_13_0_9.msi). This needs to be installed to print the voting reports from DCN-SWSMV. <p>Note</p> <ul style="list-style-type: none"> • Windows Vista is no longer supported for DCN-SW, DCN-SWSMV, DCN-SWSACC, HdCameraControl
4.30	2014-01-31	<p>New functionality and improvements</p> <ul style="list-style-type: none"> • DcnHdCameraControl added second video switcher Kramer MV-6 • DcnHdCameraControl made screen line configurable • DcnHdCameraControl added camera transition time • added create groups, rename meetings, rename sessions, request list via API (DCN-SWAPI) including demonstrator application with source code. • Support for the new audio expander PRS-4AEX4 by DCN-CCU2. <p>Fixes</p> <ul style="list-style-type: none"> • Increased the vote description from 50 to 130 characters. • Individual voting results not translated.

Release	Release Date	Release Comments
4.21	2013-09-30	<p>Fixes</p> <ul style="list-style-type: none"> • Multi channel and multi lingual DCN-SWWA (version 1.1.1) added. • Russian helpfile missing in DCN-SW. • Previous DCN-SW version cannot be upgraded because database of previous DCN-SW version cannot be upgraded.
4.20	2013-07-15	<p>New functionality and improvements</p> <ul style="list-style-type: none"> • DCN-SW added Opinion Poll and Audience Response (requires DCN-SWMV multi voting license) • Select, Summon, Start, Hold, Stop of votings via API (DCN-SWAPI) including demonstrator application with source code. • DCN-SW copy vote and copy session added to Configuration Application and API to improve usability • Master Volume Control and Chairman Priority added to Control API. • Added Vietnamese and Indonesian language to DCN-SW, DCN-SWSMV and DCN-SWSACC • Added get and set System ID for slave CCU's to Open Interface • Response list length increased from 5 to max 25 and made configurable on CCU and via DCN-SW • Number of Open Microphones (NOM) increased from 4 to 25. • Number of seats which can be added to the Notebook increased from 15 to 25. • Increased Operator Application target size • Added group speech timers to DCN-SWSMD (and DcnSmdDemonstrator application) • Added show last minute of speech by blinking microphone LED • Added a new audio routing option to the CCU: Insert no AGC. <p>Fixes</p> <ul style="list-style-type: none"> • DCN-SW added Czech, language to the installer. • Show OI connection on CCU • Solved inconsistencies in showing voting results • Solved SMD error regarding loss of speaker information when chairman speaks and ID cards and speechnimers are used. • Voting control on desktop does not show graphs for group results

Release	Release Date	Release Comments
4.10	2013-04-17	<p>New functionality and improvements</p> <ul style="list-style-type: none"> • Start/Stop Meeting and Session and Microphone Management control via API (DCN-SWAPI) including demonstrator application with source code. • Control of the IDesk outgoing channel using DCN Operator Application (requires DCN-SWSI license). • DCN-SW added Voice Activated Microphone Logging to identify which microphone is active in VOICE mode (requires DCN-SWVAML license). Can be used in combination with camera control to see who is speaking in voice mode. • DCN-SW font colour below icons on layout can be changed. • DCN-SW Meeting can be copied (including all settings) using Configuration Application and API. • Demonstrator application including source code for DCN-SWSMD XML streaming meeting data. • HD Camera Control via DCN-SWSMD streaming meeting data. • DCN-SW added Czech language to the GUI. Czech language has to be copied manually, please refer to the Tools\Language\ directory. • Extended the explanation about the TCP connection in Open Interface description. • DCN-SWWA Webcast application added. Only English User interface. Only one audio-channel/language. <p>Fixes</p> <ul style="list-style-type: none"> • DCN-SWSMD information regarding microphone on off. • DCN-SWSMD information empty when session name and description are identical. • Stopping an Operator-control session does not clear request list. • DCN-MR wave form and audio sometimes not in sync. • DCN-SW not all GUI texts fit. • DCN-SWSMV Reset microphone sensitivity ALL MICROPHONES. • DCN-CCU2 can cause acoustic feedback when powered up in Insertion mode. • DCN-SW added Slovenian language to GUI. Made Japanese helpfile part of the installer. Added Thai, Polish and Finnish language to the installer. • DCN-SWSMD Participant is made absent when Chairman speaks in Operator with response mode. • Quorum shows strange behaviour with ID-cards and Secret voting. • Performance and stability improvements on DCN SW Server and Operator Control • Delegate names are not shown in speakerlist when using access control for voting only.
4.03	2012-07-15	<p>Fixes</p> <ul style="list-style-type: none"> • DCN-SW Operator Application can cause a fault pop up upon user login and start session. • DCN-SW Configurator Application can cause a fault pop up when a document will be inserted with a file name that is too long. • DCN-SW Printing Application will not start up in Spanish, Catalan, Portuguese and Polish.

Release	Release Date	Release Comments
4.02	2012-04-16	Fixes <ul style="list-style-type: none"> Inserting or withdrawing of ID-cards could lead to fault pop up.
4.01	2012-03-01	Fixes <ul style="list-style-type: none"> Auto-relay is always activated when the B-output channel is selected (Using DCN-SW with DCN-SWSI).
4.00	2011-12-02	<ul style="list-style-type: none"> DCN-CCU2 replaces DCN-CCU, DCN-WCCU and DCN-NCO DCN-CCUB2 replaces DCN-CCUB
3.10	2011-07-26	New functionality and improvements <ul style="list-style-type: none"> Simultaneous Interpretation DCN-SWSI added Usher call and speak slowly requests support DCN-SWMD DCN-SW GUI languages: de, ca, en, es, fr, hu, it, jp, ko, lt, nl, no, pt, ru, sv, zh-chs DCN-SW help files languages: de, en, es, fr, it, nl, zh-chs Seat assignment and seat definition improved DCN-SWSACC indicates when DCN-SWSACC licenses is missing.

3 Release Compatibility Restrictions

The following versions are compatible with this release:

Product	Hw	FPGA	SW	FW
DCN-CCU2	<1.4	na	na	4.60
DCN-CCU2	1.4	na	na	4.60 ^a
DCN-CCU		1.07	--	3.1x
DCN-CCU in multi CCU mode	>=5.0	>=2.17		--
LBB 4120/00 Interpreter desk		>=1.2	--	--
Toggle in DCN-IDESK			>=1.40.xxxx	
Optical devices				5.02

Note:

- a. DCN-CCU2 with hardware 1.4 could become defective if they are downgraded below software version 4.60.

Wireless Units:

New firmware is developed for the DCN Wireless units to operate with the DCN-CCU2 (e.g. encryption functionality). This firmware can be uploaded using the Download and License Tool (DLT) and the Upgrade Toolkit (DCN-UPTK). This firmware works with DCN-CCU2 and DCN-WCCU.

Products with the following hardware version have already this firmware installed.

Product	Hw
DCN-WD-D	02/04
DCN-WDD-D	02/04
DCN-WDV-D	02/04
DCN-WDCS-D	02/05
DCN-WDDCS-D	02/05
DCN-WDVCS-D	02/05

4 Software, Firmware & FPGA versions

The table below provides a versions overview of parts which cannot be downloaded using the Download and License Tool or the DCN-UPTK Wireless upgrade Tool kit. Please contact your local Bosch representative how to update these parts.

The HW column indicates if the Hardware Version of the product is supported for the listed parts.

For product which cannot show the FPGA version, the HW version belonging to the FPGA version is shown between brackets after the FPGA version.

DCN-CCU & DCN-WCCU

FPGA	HW	Fixes
2.23	≥ 4.0	Slow reacting Multi CCU system
2.22	≥ 4.0	Noise or no audio on delegate loudspeaker
2.20	≥ 4.0	Unstable system after start-up due to optical network disturbances
2.19	≥ 4.0	Noise on delegate loudspeaker
2.18	≥ 4.0	Unexpected beeps on delegate loudspeaker fixed

DCN-CCUB

FPGA	HW	Fixes
1.22	≥ 1.0	Noise or no audio on delegate loudspeaker
1.09	≥ 1.0	Noise on delegate loudspeaker
1.08	≥ 1.0	Unexpected beeps on delegate loudspeaker

DCN-CONxx range

FPGA	HW	Fixes / Additions
1.17 (hw1.12)	≥ 1.0	Address might be lost after system restart
1.14 (hw1.10)	≥ 1.0	11Khz noise
SW		
1.10.xxxx (hw1.13)	≥ 1.0	CRC check added for ID-cards

DCN-DDI

FPGA	HW	Fixes / Additions
2.2 (hw02.01)	≥ 1.0	11Khz noise
2.0 (hw02.00)	≥ 1.0	CRC check added for ID-cards

DCN-DIS range

FPGA	HW	Problem fixed
1.20 (hw02.06)	≥ 1.0	11Khz noise
1.18 (hw02.03)	≥ 1.0	Disturbed audio on headphones for channels > 28 Address might be lost after system restart
1.15	≥ 1.0	Channel auto increment equal to DCN-CON
1.13 (hw02.02)	≥ 1.0	Audio distorted on headphones

DCN-FCS

FPGA	HW	Fixes
2.7 (hw02.02)	≥ 2.0	11Khz noise

DCN-IDESK


FPGA	HW	Fixes / Additions
2.1	≥ 2.0	11Khz noise
SW		
1.41.xxxx	≥ 1.0	loudspeaker symbol might be shown in front of the quality indicator after leaving the Idesk's installation menu
1.40.xxxx	≥ 1.0	B Toggle added

INT-TX Range

FPGA	HW	Fixes / Additions
02.03	≥ 1.0	The display might show unexpected characters
02.02	≥ 1.0	Improved stability when used in combination with the DCN system
02.01	≥ 1.0	Improved stability when used in combination with the DCN system


5 Additional Information to the DCN Manuals and Help Files



Chapter 7.13 DCN-DDI Dual Delegate Interface



9. De-init switch - Erases the address of the dual delegate interface (refer to Initialization, page 183). The red LED adjacent to the de-init switch comes on when the dual delegate interface does not have an address.
10. Input adjustment potentiometer - Adjusts the sensitivity of the audio input.
11. Input type switch - Sets the type of audio input.
 - Upper Balanced signal with phantom power
 - Center Balanced signal without phantom power
 - Lower Unbalanced signal*
12. Input adjustment switch - Sets the sensitivity of the audio input.
13. Signal level switch - Sets the signal level of the audio input.
 - Left Line level signal
 - Right Microphone signal*

Reference	What
-----------	------

Reference	What
<p>Security</p>	<p>Security measures</p> <p>The installer is responsible for security measures to prevent improper use of the system via the Internet and local wired or wireless networks.</p> <p>Think of the following items to increase security:</p> <ul style="list-style-type: none"> • Prevent unauthorized access to the Central Control Unit • Prevent unauthorized physical and logical access to the wired Ethernet connection Central Control Unit • Prevent unauthorized access to the DCN NG computer • Change the default admin password • Place the Central Control Unit in a separate VLAN <p>Use a firewall</p>
<p>Install</p>	<p>Installation error</p> <p>The installation will by default install in a database server in \SQLExpress\ If there is already a database server installed with a different name it will report the following error, because we do not want to create a new database server.</p>  <p>The screenshot shows a multi-step installation wizard. The current step is 'SQL Server Selection'. The text reads: 'The SQL Server to run the Bosch DCN Conference Software Suite Database needs to be selected.' Below this, a smaller error dialog box is open with a red 'X' icon and the message: 'Unable to connect to the configured SQL Server. Either the server name or the User name Password combination is incorrect'. At the bottom of the wizard, there are buttons for '< Back', 'Next >', and 'Cancel'. An 'OK' button is visible on the error dialog box.</p> <p>Via the OK button and the browse option you can select the already available database server.</p>

Reference	What
<p>DCN-SWAPI</p>	<p>Using the API for normal or ASP.NET environments.</p> <p>Prerequisite: Only x86 (32 bit environment) target build platforms are supported for projects.</p>  <p>The DCN-SWAPI requires to load the “Bosch.Dcn.Ecpc.Client.Logic.dll.config” file from the current folder.</p> <p>If the current folder differs from the .EXE location then the “Bosch.Dcn.Ecpc.Client.Logic.dll.config”file has to be copied to the new current folder.</p> <p>This current folder is different depending on the environment and running on 64 bit Windows:</p> <ul style="list-style-type: none"> • Normal .EXE : The location of the executable • .EXE running as service : %SystemRoot%\SysWOW64 • ASP.NET app in IISExpress : %ProgramFiles(x86)%IIS Express • ASP.NET app in IIS : %SystemRoot%\SysWOW64\inetsrv <p>Note: Applications built on x64 platform are not supported</p>
<p>DCN-SW</p>	<p>When installing DCN-SW on a Windows 7 PC you might get the following notification:</p>  <p>This is because within the time installer checks for framework, SQLServer installation starts which prompt for the framework installation. Please press OK, after this the framework will be installed from the DCN-SW installer and DCN-SW installation will install successful.</p>


Reference	What
Wireless Discussion Units	Wireless Discussion Units which are produced before 2012 need to be upgraded using the DCN-UPTK and DLT (4.xx) in order to operate with a DCN-CCU2.
DCN-SWSMV	Showing voting results in PowerPoint In case PowerPoint is used to show the voting result, it might happen that PowerPoint starts and overlaps the user interface of DCN-SWSMV completely. Use the Windows task bar to select DCN-SWSMV again.
DCN-SWSMV	Printing voting results To print voting results, Crystal Reports needs to be installed. It is located in the Tools directory of the DVD (CRRuntime_32bit_13_0_9.msi).

6 Trouble Shootings and known issues

This trouble shootings and known issues are an addition to chapter 2 and to the trouble shooting chapter in the user manuals.

Product/function	Problem	Solution
DCN-HdCameraControl	HdCameraControl has stopped working when you use Show Video on the Panasonic Camera	Installing the Windows update for Flash (KB3133431) might solve the problem. https://support.microsoft.com/en-us/help/3133431/update-for-adobe-flash-player-in-internet-explorer-and-microsoft-edge https://support.microsoft.com/en-in/help/3132372/microsoft-security-advisory-update-for-vulnerabilities-in-adobe-flash Otherwise use your browser to configure the Panasonic camera.
DCN-HdCameraControl	Panasonic Camera: Preset number is not equal to preset number in the webbrowser of the camera	Camera browser preset 1 corresponds with HdCameraControl preset 0 for the Panasonic camera. Calculate with an offset of 1.
DCN-SWAT	Attendance registration does not work with Thai as Operating system.	Change from using the Thai-Buddhist calendar to using the Gregorian calendar.
DCN-SW service does not start automatically	Security setting in Windows 10 can prevent that the services start.	Grant administrative rights to the server.exe application for all users.
DCN-SW control microphone sensitivity of DCN-IDESK	When changing the sensitivity of the microphone of the DCN-IDESK will result in short audio clicks.	No solution available Audio clicks are only heard while increasing or decreasing microphone sensitivity of DCN-IDESK.
DCN-SW Configuration Application	In rare occasions it can happen that the application closes unintended.	Restart the DCN-SW Configuration Application.
DCN-SW rinting individual voting results manually	Individual voting results are not printed when printed manually via Bosch DCN SW Print Application.	Change the voting template accordingly: <ol style="list-style-type: none"> 1. Check the "Automatic print after stop of the voting" checkbox. 2. Change the settings to Total, groups and individuals. 3. Uncheck "Automatic print after stop of the voting" checkbox.

Product/function	Problem	Solution
DCN-SW multi PC	Client cannot connect with Server when multiple network adapters are available	Configure the adapter settings in such a way that the network adapter which is used for DCN NG is the highest in the list of connections in Adapters and Bindings
DCN-SW multi PC	Connection between DCN server and operator client will disconnect. This is occurring when using windows 10 PC's with SSD-disks.	In windows 10 there is the option enabled to store some services when the system has been shut down and start up again. This can cause problems with our services: Disable fast start-up option in the win 10 PC: <ul style="list-style-type: none"> • go to the control panel of windows • then go to 'power options' • then click on 'choose what the power buttons do' • then click on 'Change settings that are currently unavailable' • then disable 'Turn on fast startup' Also the use of an SSD disk in the server PC can cause some startup problems with the DCN-NG software. To fix this: <ul style="list-style-type: none"> • go to the services • right-click on 'DCN-SW Server' • click on 'Properties' • Change startup type to Automatic (Delayed start) Now restart the PC and test with these settings.
DCN-SW	Delegate both in Request to speak as Request to respond list.	If a delegate is both in the Request to Respond as in the Request to Speak list and you want to shift the Request to Speak to Speaking, first cancel the Request to Respond.
DCN-SW	On 64-bit operating systems, it might difficult to find previous SQL-server during DCN-SW installation, when initial SQL-installation was not default.	During installation of DCN-SW the installation process might not be able to find the previous SQL-server, in case during initial installation another name for the SQL-server was created, instead of using the default name. Therefore it is recommended to use the default name and folder during initial SQL-installation. If a SQL-server with a non-default name needs to be found, the correct name should be entered manually in the applicable box during DCN-SW installation.
DCN-SW	System overview does not show all connected devices when system is still powering up.	Wait until DCN-system is powered up completely and then check the connected devices via DCN-SW configuration application VIEW \ System Overview.
DCN-SW	DCN-SW Master Volume is different from CCU volume control	When the Master Volume of the CCU has been changed while DCN-SW was disconnected, the DCN-SW Master Volume will not reflect the CCU-setting. Changing the DCN-SW volume setting, will make them identical again.
DCN-SW	Downgrade to versions <3.10 not possible.	Manually uninstall SWL server 2008. Note that the DCN-SW database (the database contains all settings like seats, meetings, synoptic layouts, etc.) will always be removed during a downgrade.

Product/function	Problem	Solution
DCN-SW	Unexpected behaviour or no reaction of DCN-SW.	Due to Windows Automatic Updates some critical components like SQL Server Express might be temporarily not available for DCN-SW. Do not set Automatic Updates to Automatic or restart your system after the Automatic updates have been installed.
DCN-SW	Generates errors after Windows Stand by..	Disable Stand by functionality in the Windows operating system.
DCN-SWPV	Secret mode does not work in ad-hoc voting	Update to version 2.80 or higher
DCN-SWPV	Voting attention tone cannot be changed during a running meeting.	The voting attention tone can be changed in the voting template but becomes effective after a vote has been selected or started.
DCN-SW setup repair	Error code 2869 or Fatal error during installation.	Remove DCN-SW with DCN-SW setup and make a new installation. Settings are stored in the SQL-database and can be re-used in the new installation.
DCN-SWSMV	Error notification upon closing DCN-SWSMV directly after opening it. 	Please wait at least 10 seconds to close DCN-SWSMV after opening it.
DCN-SWSMV help file	When opening help file you get an error.	Just close the error notification.
DCN-SWSMV	DCN-SWSMV will not start	Voting legends cannot be changed into "Not Voted". Remove "BCPCSettings.xml" which can be found: For XP: "...\\Documents and Settings\\All Users\\Application Data\\Bosch\\DCN Synoptic Microphone and Voting Software\\x.xx" For Vista: "...\\Programdata\\Bosch\\DCN Synoptic Microphone and Voting Software\\x.xx"
Wired and wireless system in combination with Integrus	No audio on DCN wired and wireless units when powering up DCN-CCU2 and Integrus transmitter simultaneous.	First power up the DCN-CCU2. After it is powered up, power up the Integrus transmitter. Note: in a system with DCN-CCU2 and other optical devices; always first power up the DCN-CCU2 before powering other optical devices.

Product/function	Problem	Solution
Not able to download DCN-CCU2 firmware	DCN-DLT is not able to download the firmware of the CCU	<p>Check if the DCN-SW server is not running:</p> <ol style="list-style-type: none"> 1. Exit the DCN-DLT program 2. Check if the DCN-CCU2 does not report PC on it's display. If it does Stop the DCN-SW server via Start\ <Search programs and files> SERVICES. Services (local). And check if PC disappears. 3. Start DCN-DLT (PC will now re-appear in the CCU2 screen, but that is correct) and start the download. <p>If the download still fails, do the following:</p> <ol style="list-style-type: none"> 1. Power off and open the DCN-CCU2 2. Set switch 8 of S600 to ON and power on the CCU. 3. Download the CCU using the DCN-DLT. 4. After a succesfull download, power off the CCU, set switch 8 of S600 to OFF again and power on the CCU.
HD Conference Dome	The HD Conference Dome will show an incorrect name & picture combination if a new pre-position is asked before it reaches it's pre-position.	Do not activate another microphone until the HD Conference Dome has reached it's pre-position.
DCN-UPTK	The type of the unit connected to the UPTK is not valid.	This notification can occur when the DCN-UPTK unit is used extensively. Please replace the connection cable.
DCN-CCU(B)2	Error relays activated upon system reset or firmware download.	During a firmware download or system reset, the system is not in normal operation and thus the error relays can be active.
DCN-CONFF and DCN-CONCM	DNPV answers in voting are not visible in the Concentus screen when a voting timer is activated.	Use a hall display or disable the voting timer.
DCN-SWSACC and Allegiant	Double screenlines are still visible on audience screens after switching to single screenlines.	Restart the Allegiant.
DCN-SWSACC	Upload does not work anymore.	Restart the DCN-CCU or DCN-NCO.

Product/function	Problem	Solution
DCN-MR	DCN-CCU(B)2 goes to Open mode after closing DCN-MR application.	<p>In a system where:</p> <ol style="list-style-type: none"> 1. The DCN-CCU(B)2 is connected to DCN-SW or DCN-SWSMV and 2. Connected to DCN-MR via Open Interface and 3. The CCU is in Operator mode. <p>It will go to Open mode if:</p> <ul style="list-style-type: none"> • It loses connection with DCN-MR (e.g. the application is stopped) <p>To restore the microphone mode to Open mode, the microphone mode needs to be set to Open mode via DCN-SW or DCN-SWSMV.</p> <p>Note: it will also go to Open mode if it loses connection with DCN-SW or DCN-SWSMV. So that the meeting can still continue.</p>
DCN-MR	DCN-MR does not connect to DCN-SW when installed on another PC	<ol style="list-style-type: none"> 1. Open the Meeting Recorder.ini file with notepad it is located here: C:\Users\[USER NAME]\AppData\Roaming\Meeting Recorder if the user name is administrator, the path will be: C:\Users\Administrator\AppData\Roaming\Meeting Recorder 2. Find the variable NCO Ip=x.x.x.x (where x.x.x.x is the IP address of DCN SW server) and below that line; Create a line DCO Ip=x.x.x.x (where x.x.x.x is the IP address of the DCN SW server) NCO Port=20000 NCO Ip=10.120.22.230 DCO Ip=10.120.22.230 CCU Ip=192.168.1.1 3. Save the Meeting Recorder.ini file
DCN-MR	Windows audio playback is lost after installation DCN-MR 1.3. in windows XP.	Replace files msacm32.driv, msadp32.acm and imaadp32.acm in the windows system32 folder.
Multi CCU systems	System reaction is (very) slow after system startup.	The system might become (very) slow when in a multi CCU system only the NCO is switched off and the rest of the system stays switched on. To prevent this problem: Shutdown all optical devices in the Multi-CCU system.

Product/function	Problem	Solution
DCN-NCO	DCN-NCO cannot be downgraded or upgraded.	<p>A known issue is that DCN-NCO cannot be downgraded from SW 2.70.</p> <p>Workaround</p> <ol style="list-style-type: none"> 1) Install the Download and License Tool of the version you want to use to downgrade or upgrade to. 2) Open Notepad and paste the text below into Notepad <pre> user target password cd /rfa dele PDSDATA1.PDS dele PDSDATA2.PDS bin hash cd /rfa/drv put mmu_3.bit put mif_3.bit cd /bim put dune.bim bye </pre> <ol style="list-style-type: none"> 3) Save the file in Notepad to C:\Program Files\Bosch\Digital Congress Network\Download and License Tool\Files with name dcn-nco.txt 4) Switch off the NCO and set dipswitch 1 of S3 to on, set all other switches to off 5) Switch on the NCO 6) Open a command prompt (start -> run -> cmd) and change to the following folder: C:\Program Files\Bosch\Digital Congress Network\Download and License Tool\Files 7) Download the NCO with the next command line FTP with the command: <i>ftp -n -s:dcn-nco.txt x.x.x.x</i> Where x.x.x.x is the IP-address of the NCO 8) Switch off the NCO and set the dipswitches all to off 9) Switch on the NCO 10) Start the Download and License Tool and start a NCO download.
DCN-CCU DCN-NCO	Local floor muted after download of NCO or CCU	Switch off and on the CCU or NCO
DCN-NCO DCN-CCU, INT-TX04/08/16/32	Unexpected behavior when adding powered system units to the optical ring	In case system units are added to the optical ring when the system is powered on, unexpected behavior can occur. Only connect units to the optical network when all units are powered off.
DCN NCO DCN-CCU INT-TX04/08/16/32	Audio disruption when switching on a transmitter	Select the option "enabled" in menu 4b (network mode).
DCN NCO DCN-CCU INT-TX04/08/16/32	Audio disruption when one of the CCUs is in the mode "--"	Change the slave id "--" to a number. (refer to menu 7I Multi Mode).

Product/function	Problem	Solution
INT-TX04/0816/32	The transmitter displays the message "No Network"	Connect a powered DCN Next Generation or DCN wireless system to the transmitter or select the option "standalone" in menu 4b (network mode)
INT-RX04/08/32	Charging indicator on the receiver is blinking	Check whether the receiver is still working correctly. If this is the case: the battery pack is fully charged and can be recharged after using it a while. If this is not the case: follow the instructions as given in the troubleshooting table.
DCN-CCU	DCN-CCU shows "Multi" while acting in "Single"	When changing from "single" to "multi" mode, the DCN-CCU can remain working in "single" mode. If this is the case follow next procedure: 1. Select "multi" on all connected CCUs 2. Switch off all CCUs. 3. Reset to defaults the NCO. 4. Switch on all CCUs.
DCN-CCU	Audio disruption during powering up/down a CCU in a Multi CCU system	During powering up/down a CCU in a Multi CCU system the audio on the delegate units, connected to the remaining CCU's, is shortly disrupted for 1 to 2 seconds.
DCN-CCU	Loss of settings after reboot of NCO in a Multi CCU system	In case the Network Controller (NCO) in a Multi CCU system is rebooted, the settings and configurations changed during the past 30 seconds can be lost. When configuring interpreter desks wait minimum 30 seconds before reboot the NCO.
LBB 4402/00 LBB 4404/00 PRS-4DEX4	Input routing does not work after download of optical devices	Change all inputs to CH00 and then to the required channel.
INT-TX	Transmitter does not work after updating firmware	Update FPGA to version 2.03 or higher Alternative solution: Update firmware of the INT-TX to version 2.80
DCN-IDENC	DCN-IDENC ID card encoder in not recognized in DCN-SW.	If other card readers/encoders are present or connected to the PC please disable them. Internal readers/encoders can be disabled in the BIOS or in the Windows Device Manager.
CNConfig	Error during installation "...verify that you have access to the directory."	Ensure that you have the required administrator rights. Restart installation.