DCN Next Generation 4.70 Release Notes





en | Release Notes



DCN Next Generation Release 4.70

Table of Contents

1	This release Contains	2
2	Improved and added Functionality	2
3		
4	Software, Firmware & FPGA versions	
5		
6	Trouble Shootings and known issues	

1 This release Contains

The following versions are part of this release:

Product	version	Windows 7 ^a	Windows 8.1 ^a	Windows 10 ^a
DCN-SW	4.70	Yes	Yes	Yes
DCN-SWSMV	4.40	Yes ^b	Yes ^b	Yes ^b
DCN-SWSACC	4.40	Yes	Yes	Yes
DCN-DLT (for CCU2)	4.70	Yes	Yes	Yes
DCN-CCU2	4.70	NA	NA	NA
HdCameraControl	4.70	Yes	Yes	Yes
DCN-DLT (for CCU, NCO)	3.10	Yes	No	No
DCN-CCU	3.10	NA	NA	NA
DCN-MR	2.30	Yes	No	No

Notes:

- a. home editions of Windows 7, 8.1, or 10 are not supported.
- b. DCN-SWSMV: exporting voting results to PowerPoint is only supported for PowerPoint 2003.

2 Improved and added Functionality

Release	Release	Release Comments
	Date	
4.70	2018-08-15	New functionality and improvements
		 Added support for Panasonic IP cameras via CGI protocol (HD Integrated Camera Interface Specifications 1.06): AW-HE40, AW-HE50, AW-HE60, AW-HE120, AW-HE130, AW-UE70. Screentext does not function with the Panasonic cameras. Added support for Sony IP cameras via CGI commands for 300/360 series: Sony SRG-300SE/301SE and SRG-360SHE. Screentext does not function with the Sony camera. Improved PIN code behaviour of devices. Fixed DCN-SW Operator client stops functioning when another Operator client disconnects. Fixed HdCameraControl disconnects from Kramer switch after a long time.
4.63	2017-11-29	New functionality and improvements
	, and the second	 Improved calibration behaviour of the optical network upon booting and adding and removing devices from the optical network.

Release	Release Date	Release Comments
4.62	2017-10-13	New functionality and improvements • Fixed DCN-SW cannot be installed on PC with Windows 10. Microsoft SQL2014 will be installed with new installations. In case of upgrades the existing SQL 2008 will be used.
4.61	2016-9-17	New functionality and improvements Fixed Slave CCU resetting issue due to time out, by increasing the time out value.
4.60	2016-7-20	 New functionality and improvements Fixed DCN-SW server front end application and DCN-SW printing application do not start on French, Portuguese and Spanish Windows. Fixed issues with streaming meeting data in combination with display application and or DCN meeting recorder. Fixed notebook behaviour of devices. Updated CCU2 firmware to support DCN-CCU2 and DCN-CCUB2 hardware version HW01/04. Improved DCN Meeting Recorder in combination with
4.50	2015-11-16	streaming meeting data. New functionality and improvements
		 Windows 10 supported. Added Hungarian translations Concentus. Fixed time stamp problem of DCN-MR Remote control via Open Interface for all (Audio) expanders. (Digital IO contacts) Remote configuration via Open Interface of all expanders, AEX, DEX, CIN,OMI; (Routing of the DCNNG floor and languages to all in- and outputs) Level control for Omneo Media Interface Microphone detection for Interpreter desk (internal, external, auto) via DCN-CCU2 front panel tvONE C2-6204A with 4 HD-SDI inputs is supported in HDCameraControl as successor of the tvONE C2-2355A / S2-108HD combination Removed Webcasting software and manuals from the DVD
4.43	2015-05-15	 New functionality and improvements Fixed: Notification of disconnection from the Bosch DCN Conference Software. Fixed: Operator application shows error and red cross after setting the Central Control Unit to Standby Changed error message when an ID card reader cannot read ID card into understandable text. Fixed: Discussion unit cannot be controlled from synoptic after a reboot of the CCU. Fixed: Language configuration in DCN-IDESK does not change with meeting after a reboot of the CCU. Improved startup behaviour of Integrus transmitter. Improved Mongolian translations on Concentus. Support of new AD convertor in Integrus Transmitter.

Release	Release Date	Release Comments
4.42	2015-03-18	New functionality and improvements Fixed delay of voting results via SMD if a vote is cast during the start chime Fixed first vote is not exported via SMD Fixed card production settings fall back to CRC after opening and closing the card production settings Fixed error upon closing Configuration Application after producing cards during a running meeting
		 Fixed DCN-SW does not install on Turkish OS Fixed focus/control goes to prepared votings when a adhoc voting is started Fixed problem with Black Magic card (due to new Black Magic drivers) in DCN-SWWA webcasting Fixed problem with pause behavior of DCN Meeting Recorder
4.41	2014-11-02	New functionality and improvements Improved DCN wireless firmware to make it more robust in environments with a lot of WiFi communication Unresponsive microphone control in Operator application due to network disconnections Added DCN-SW icons to DVD
4.40	2014-07-30	 New functionality and improvements Added Notebooker configuration to the API and DcnApiDemonstrator Added AGC on/off to audio outputs of Audio Expander in Individual Channels mode DCN-CCU2 supports Omneo Media Interface (PRS4OMI4) to interface with DCN multimedia Added Mongolian to Concentus display ID cards can be programmed via API with and without CRC Insert and remove of ID card can be executed via API to enable interfacing with third party identification system Windows 8.1 support for DCN-SW Windows 8.1 support for DCN-SWSMV Windows 8.1 support for DCN-SWSACC Windows 8.1 support for HdCameraControl Added Crystal Reports installer to Tools directory (CRRuntime_32bit_13_0_9.msi). This needs to be installed to print the voting reports from DCN-SWSMV. Note Windows Vista is no longer supported for DCN-SW, DCN-SWSMV, DCN-SWSACC, HdCameraControl
4.30	2014-01-31	New functionality and improvements DcnHdCameraControl added second video switcher Kramer MV-6 DcnHdCameraControl made screen line configurable DcnHdCameraControl added camera transition time added create groups, rename meetings, rename sessions, request list via API (DCN-SWAPI) including demonstrator application with source code. Support for the new audio expander PRS-4AEX4 by DCN-CCU2. Fixes Increased the vote description from 50 to 130 characters. Indivual voting results not translated.

Release	Release	Release Comments
4.01	Date	The state of the s
4.21	2013-09-30	Fixes
		Multi channel and multi lingual DCN-SWWA (version 1.1.1)
		added.
		Russian helpfile missing in DCN-SW.
		Previous DCN-SW version cannot be upgraded because
4.00	0010 07 15	database of previous DCN-SW version cannot be upgraded.
4.20	2013-07-15	New functionality and improvements
		DCN-SW added Opinion Poll and Audience Response (requires DCN SW/M) resulting lineage
		(requires DCN-SWMV multi voting license)
		Select, Summon, Start, Hold, Stop of votings via API (DCN-SN/API) in all visits and appropriate to a publication with a sure and a selection with a selec
		SWAPI) including demonstrator application with source code.
		DCN-SW copy vote and copy session added to Configuration Application and API to improve usability.
		 Application and API to improve usability Master Volume Control and Chairman Priority added to Control
		API.
		Added Vietnamese and Indonesian language to DCN-SW,
		DCN-SWSMV and DCN-SWSACC
		Added get and set System ID for slave CCU's to Open
		Interface
		Response list length increased from 5 to max 25 and made
		configurable on CCU and via DCN-SW
		 Number of Open Microphones (NOM) increased from 4 to 25.
		Number of seats which can be added to the Notebook
		increased from 15 to 25.
		Increased Operator Application target size
		 Added group speech timers to DCN-SWSMD (and
		DcnSmdDemonstrator application)
		 Added show last minute of speech by blinking microphone LED
		 Added a new audio routing option to the CCU: Insert no AGC.
		Fixes
		 DCN-SW added Czech, language to the installer.
		Show OI connection on CCU
		 Solved inconsistencies in showing voting results
		 Solved SMD error regarding loss of speaker information when
		chairman speaks and ID cards and speechtimers are used.
		 Voting control on desktop does not show graphs for group
		results

Release	Release Date	Release Comments
4.10		New functionality and improvements Start/Stop Meeting and Session and Microphone Management control via API (DCN-SWAPI) including demonstrator application with source code. Control of the IDesk outgoing channel using DCN Operator Application (requires DCN-SWSI license). DCN-SW added Voice Activated Microphone Logging to identify which microphone is active in VOICE mode (requires DCN-SWVAML license). Can be used in combination with camera control to see who is speaking is voice mode. DCN-SW font colour below icons on layout can be changed. DCN-SW Meeting can be copied (including all settings) using Configuration Application and API. Demonstrator application including source code for DCN-SWSMD XML streaming meeting data. HD Camera Control via DCN-SWSMD streaming meeting data. DCN-SW added Czech language to the GUI. Czech language has to be copied manually, please refer to the Tools\Language\directory. Extended the explanation about the TCP connection in Open Interface description. DCN-SWWA Webcast application added. Only English User interface. Only one audio-channel/language. Fixes DCN-SWSMD information regarding microphone on off. DCN-SWSMD information empty when session name and description are identical. Stopping an Operator-control session does not clear request list. DCN-SW not all GUI texts fit. DCN-SWSMV Reset microphone sensitivity ALL MICROPHONES. DCN-SWSMV Reset microphone sensitivity ALL MICROPHONES. DCN-SWSMD Participant is made absent when Chairman speaks in Operator with response mode. DCN-SWSMD porator with response mode. Quorum shows strange behaviour with ID-cards and Secret voting.
		 Performance and stability improvements on DCN SW Server and Operator Control Delegate names are not shown in speakerlist when using access control for voting only.
4.03	2012-07-15	 Fixes DCN-SW Operator Application can cause a fault pop up upon user login and start session. DCN-SW Configurator Application can cause a fault pop up when a document will be inserted with a file name that is too long. DCN-SW Printing Application will not start up in Spanish, Catalan, Portuguese and Polish.

Release	Release	Release Comments	
	Date		
4.02	2012-04-16	Fixes	
		 Inserting or withdrawing of ID-cards could lead to fault pop up. 	
4.01	2012-03-01	Fixes	
		 Auto-relay is always activated when the B-output channel is 	
		selected (Using DCN-SW with DCN-SWSI).	
4.00	2011-12-02	DCN-CCU2 replaces DCN-CCU, DCN-WCCU and DCN-NCO	
		DCN-CCUB2 replaces DCN-CCUB	
3.10	2011-07-26	New functionality and improvements	
		Simultaneous Interpretation DCN-SWSI added	
		 Usher call and speak slowly requests support DCN-SWMD 	
		 DCN-SW GUI languages: de, ca, en, es, fr, hu, it, jp, ko, lt, nl, 	
		no, pt, ru, sv, zh-chs	
		DCN-SW help files languages: de, en, es, fr, it, nl, zh-chs	
		Seat assignment and seat definition improved	
		DCN-SWSACC indicates when DCN-SWSACC licenses is	
		missing.	

3 Release Compatibility Restrictions

The following versions are compatible with this release:

Product	Hw	FPGA	SW	FW
DCN-CCU2	<1.4	na	na	4.60
DCN-CCU2	1.4	na	na	4.60 ^a
DCN-CCU		1.07		3.1x
DCN-CCU in multi CCU mode	>=5.0	>=2.17		
LBB 4120/00 Interpreter desk		>=1.2		
Toggle in DCN-IDESK			>=1.40.xxxx	
Optical devices				5.02

Note:

a. DCN-CCU2 with hardware 1.4 could become defective if they are downgraded below software version 4.60.

Wireless Units:

New firmware is developed for the DCN Wireless units to operate with the DCN-CCU2 (e.g. encryption functionality). This firmware can be uploaded using the Download and License Tool (DLT) and the Upgrade Toolkit (DCN-UPTK). This firmware works with DCN-CCU2 and DCN-WCCU.

Products with the following hardware version have already this firmware installed.

Product	Hw
DCN-WD-D	02/04
DCN-WDD-D	02/04
DCN-WDV-D	02/04
DCN-WDCS-D	02/05
DCN-WDDCS-D	02/05
DCN-WDVCS-D	02/05

4 Software, Firmware & FPGA versions

The table below provides a versions overview of parts which cannot be downloaded using the Download and License Tool or the DCN-UPTK Wireless upgrade Tool kit. Please contact your local Bosch representative how to update these parts.

The HW column indicates if the Hardware Version of the product is supported for the listed parts.

For product which cannot show the FPGA version, the HW version belonging to the FPGA version is shown between brackets after the FPGA version.

DCN-CCU & DCN-WCCU

FPGA	HW	Fixes	
2.23	≥ 4.0	Slow reacting Multi CCU system	
2.22	≥ 4.0	Noise or no audio on delegate loudspeaker	
2.20	≥ 4.0	Unstable system after start-up due to optical network disturbances	
2.19	≥ 4.0	Noise on delegate loudspeaker	
2.18	≥ 4.0	Unexpected beeps on delegate loudspeaker fixed	

DCN-CCUB

FPGA	HW	Fixes	
1.22	≥ 1.0	Noise or no audio on delegate loudspeaker	
1.09	≥ 1.0	Noise on delegate loudspeaker	
1.08	≥ 1.0	Unexpected beeps on delegate loudspeaker	

DCN-CONxx range

FPGA	HW	Fixes / Additions	
1.17 (hw1.12)	≥ 1.0	Address might be lost after system restart	
1.14 (hw1.10)	≥ 1.0	11Khz noise	
SW			
1.10.xxxx (hw1.13)	≥ 1.0	CRC check added for ID-cards	

DCN-DDI

FPGA	HW	Fixes / Additions	
2.2 (hw02.01)	≥ 1.0	11Khz noise	
2.0 (hw02.00)	≥ 1.0	CRC check added for ID-cards	

DCN-DIS range

2 011 210 1411 80			
FPGA	HW	Problem fixed	
1.20 (hw02.06)	≥ 1.0	11Khz noise	
1.18 (hw02.03)	≥ 1.0	Disturbed audio on headphones for channels > 28	
		Address might be lost after system restart	
1.15	≥ 1.0	Channel auto increment equal to DCN-CON	
1.13 (hw02.02)	≥ 1.0	Audio distorted on headphones	

DCN-FCS

FPGA	HW	Fixes
2.7 (hw02.02)	≥ 2.0	11Khz noise

DCN-IDESK


FPGA	HW	Fixes / Additions
2.1	≥ 2.0	11Khz noise
SW		
1.41.xxxx	≥ 1.0	loudspeaker symbol might be shown in front of the quality indicator after leaving the Idesk's installation menu
1.40.xxxx	≥ 1.0	B Toggle added

INT-TX Range

FPGA	HW	Fixes / Additions	
02.03	≥ 1.0	The display might show unexpected characters	
02.02	≥ 1.0	Improved stability when used in combination with the DCN system	
02.01	≥ 1.0	Improved stability when used in combination with the DCN system	


5 Additional Information to the DCN Manuals and Help Files


Chapter 7.13 DCN-DDI Dual Delegate Interface



- 9. De-init switch Erases the address of the dual delegate interface (refer to Initialization, page 183). The red LED adjacent to the de-init switch comes on when the dual delegate interface does not have an address.
- 10. Input adjustment potentiometer Adjusts the sensitivity of the audio input.
- 11. Input type switch Sets the type of audio input.
 - Upper Balanced signal with phantom power
 - Center Balanced signal without phantom power
 - Lower Unbalanced signal*
- 12. Input adjustment switch Sets the sensitivity of the audio input.
- 13. Signal level switch Sets the signal level of the audio input.
 - Left Line level signal Right Microphone signal*

Reference	What





Reference	What
DCN-SWSMV	Printing voting results
	To print voting results, Crystal Reports needs to be installed. It is located in the
	Tools directory of the DVD (CRRuntime_32bit_13_0_9.msi).

6 Trouble Shootings and known issues

This trouble shootings and known issues are an addition to chapter 2 and to the trouble shooting

chapter in the user manuals.

Product/function	Problem	Solution
DCN- HdCameraControl	HDCameraControl has stopped working when you use Show Video on the Panasonic Camera	Installing the Windows update for Flash (KB3133431) might solve the problem. https://support.microsoft.com/en- us/help/3133431/update-for-adobe-flash-player-in- internet-explorer-and-microsoft-edge https://support.microsoft.com/en- in/help/3132372/microsoft-security-advisory-update- for-vulnerabilities-in-adobe-flash Otherwise use your browser to configure the Panasonic camera.
DCN-SW control microphone sensitivity of DCN-IDESK	When changing the sensitivity of the microphone of the DCN-IDESK will result in short audio clicks.	No solution available Audio clicks are only heard while increasing or decreasing microphone sensitivity of DCN-IDESK.
DCN-SW Configuration Application	In rare occasions it can happen that the application closes unintended.	Restart the DCN-SW Configuration Application.
DCN-SW rinting individual voting results manually	Individual voting results are not printed when printed manually via Bosch DCN SW Print Application.	 Change the voting template accordingly: Check the "Automatic print after stop of the voting" checkbox. Change the settings to Total, groups and individuals. Uncheck "Automatic print after stop of the voting" checkbox.
DCN-SW multi PC	Client cannot connect with Server when multiple network adapters are available	Configure the adapter settings in such a way that the network adapter which is used for DCN NG is the highest in the list of connections in Adapters and Bindings
DCN-SW	Delegate both in Request to speak as Request to respond list.	If a delegate is both in the Request to Respond as in the Request to Speak list and you want to shift the Request to Speak to Speaking, first cancel the Request to Respond.
DCN-SW	On 64-bit operating systems, it might difficult to find previous SQL-server during DCN-SW installation, when initial SQL-installation was not default.	During installation of DCN-SW the installation process might not be able to find the previous SQL-server, in case during initial installation another name for the SQL-server was created, instead of using the default name. Therefore it is recommended to use the default name and folder during initial SQL-installation. If a SQL-server with a non-default name needs to be found, the correct name should be entered manually in the applicable box during DCN-SW installation.

Product/function	Problem	Solution
DCN-SW	System overview	Wait until DCN-system is powered up completely and
	does not show all	then check the connected devices via DCN-SW
	connected devices	configuration application VIEW \ System Overview.
	when system is still	
	powering up.	
DCN-SW	DCN-SW Master	When the Master Volume of the CCU has been
	Volume is different	changed while DCN-SW was disconnected, the DCN-
	from CCU volume	SW Master Volume will not reflect the CCU-setting.
	control	Changing the DCN-SW volume setting, will make
		them identical again.
DCN-SW	Downgrade to	Manually uninstall SWL server 2008.
	versions <3.10 not	Note that the DCN-SW database (the database
	possible.	contains all settings like seats, meetings, synoptic
		layouts, etc.) will always be removed during a
		downgrade.
DCN-SW	Unexpected	Due to Windows Automatic Updates some critical
	behaviour or no	components like SQL Server Express might be
	reaction of DCN-SW.	temporarily not available for DCN-SW.
		Do not set Automatic Updates to Automatic or restart
		your system after the Automatic updates have been
		installed.
DCN-SW	Generates errors after	Disable Stand by functionality in the Windows
	Windows Stand by	operating system.
DCN-SWPV	Secret mode does not	Update to version 2.80 or higher
	work in ad-hoc voting	
DCN-SWPV	Voting attention tone	The voting attention tone can be changed in the
	cannot be changed	voting template but becomes effective after a vote has
	during a running	been selected or started.
	meeting.	
DCN-SW setup	Error code 2869 or	Remove DCN-SW with DCN-SW setup and make a
repair	Fatal error during	new installation. Settings are stored in the SQL-
	installation.	database and can be re-used in the new installation.
DCN-SWSMV	Error notification upon	Please wait at least 10 seconds to close DCN-
	closing DCN-SWSMV	SWSMV after opening it.
	directly after opening	
	it.	
	Bosch DCN-SWSMV Open the Crystal Report template file failed.	
	OK	
DCN-SWSMV help		Just close the error notification.
file	When opening help file you get an error.	oust close the entit hothication.
DCN-SWSMV	DCN-SWSMV will not	Voting legends cannot be changed into "Not Voted".
DOIN DANDINIA	start	Remove "BCPCSettings.xml" which can be found:
	Juit	For XP:
		"\Documents and Settings\All Users\Application
		Data\Bosch\DCN Synoptic Microphone and Voting
		Software\x.xx"
		For Vista:
		"\Programdata\Bosch\DCN Synoptic Microphone
		and Voting Software\x.xx"
Wired and wireless	No audio on DCN	First power up the DCN-CCU2. After it is powered up,
system in	wired and wireless	power up the Integrus transmitter.
combination with	units when powering	Note: in a system with DCN-CCU2 and other optical
Integrus	up DCN-CCU2 and	devices; always first power up the DCN-CCU2 before
	Integrus transmitter	powering other optical devices.
	simultaneous.	
		1

Product/function	Problem	Solution
Not able to	DCN-DLT is not able	Check if the DCN-SW server is not running:
download DCN-CCU2 firmware	to download the firmware of the CCU	 Exit the DCN-DLT program Check if the DCN-CCU2 does not report PC on it's display. If it does Stop the DCN-SW server via Start\ <search and="" files="" programs=""> SERVICES. Services (local). And check if PC disappears.</search> Start DCN-DLT (PC will now re-appear in the CCU2 screen, but that is correct) and start the download. If the download still fails, do the following: Power off and open the DCN-CCU2 Set switch 8 of S600 to ON and power on the CCU. Download the CCU using the DCN-DLT.
		 After a succesfull download, power off the CCU, set switch 8 of S600 to OFF again and power on the CCU.
HD Conference Dome	The HD Conference Dome will show an incorrect name & picture combination if a new pre-position is asked before it reaches it's pre- position.	Do not activate another microphone until the HD Conference Dome has reached it's pre-position.
DCN-UPTK	The type of the unit connected to the UPTK is not valid.	This notification can occur when the DCN-UPTK unit is used extensively. Please replace the connection cable.
DCN-CCU(B)2	Error relays activated upon system reset or firmware download.	During a firmware download or system reset, the system is not in normal operation and thus the error relays can be active.
DCN-CONFF and DCN-CONCM	DNPV answers in voting are not visible in the Concentus screen when a voting timer is activated.	Use a hall display or disable the voting timer.
DCN-SWSACC and Allegiant	Double screenlines are still visible on audience screens after switching to single screenlines.	Restart the Allegiant.
DCN-SWSACC	Upload does not work anymore.	Restart the DCN-CCU or DCN-NCO.

Product/function	Problem	Solution
DCN-MR	DCN-CCU(B)2 goes to Open mode after closing DCN-MR application.	In a system where: 1. The DCN-CCU(B)2 is connected to DCN-SW or DCN-SWSMV and 2. Connected to DCN-MR via Open Interface and 3. The CCU is in Operator mode. It will go to Open mode if: It loses connection with DCN-MR (e.g. the application is stopped) To restore the microphone mode to Open mode, the microphone mode needs to be set to Open mode via DCN-SW or DCN-SWSMV. Note: it will also go to Open mode if it loses connection with DCN-SW or DCN-SWSMV. So that the meeting can still continue.
DCN-MR	DCN-MR does not connect to DCN-SW when installed on another PC	 Open the Meeting Recorder.ini file with notepad it is located here: C:\Users\[USER NAME]\AppData\Roaming\Meeting Recorder if the user name is administrator, the path will be: C:\Users\ Administrator\AppData\Roaming\Meeting Recorder Recorder Find the variable NCO Ip=x.x.x.x (where x.x.x.x is the IP address of DCN SW server) and below that line; Create a line DCO Ip=x.x.x.x (where x.x.x.x is the IP address of the DCN SW server) NCO Port=20000 NCO Ip=10.120.22.230 DCO Ip=10.120.22.230 CCU Ip=192.168.1.1 Save the Meeting Recorder.ini file
DCN-MR	Windows audio playback is lost after installation DCN-MR 1.3. in windows XP.	Replace files msacm32.drv, msadp32.acm and imaadp32.acm in the windows system32 folder.
Multi CCU systems	System reaction is (very) slow after system startup.	The system might become (very) slow when in a multi CCU system only the NCO is switched off and the rest of the system stays switched on. To prevent this problem: Shutdown all optical devices in the Multi-CCU system.

Product/function	Problem	Solution
DCN-CCU DCN-	DCN-NCO cannot be downgraded or upgraded.	A known issue is that DCN-NCO cannot be downgraded from SW 2.70.
	upgraueu.	 Workaround 1) Install the Download and License Tool of the version you want to use to downgrade or upgrade to. 2) Open Notepad and paste the text below into Notepad
		user target password cd /rfa dele PDSDATA1.PDS dele PDSDATA2.PDS bin hash cd /rfa/drv put mmu_3.bit put mif_3.bit cd /bim put dune.bim bye
	Local floor muted after	 Save the file in Notepad to C:\Program Files\Bosch\Digital Congress Network\Download and License Tool\Files with name dcn-nco.txt Switch off the NCO and set dipswitch 1 of S3 to on, set all other switches to off Switch on the NCO Open a command prompt (start -> run -> cmd) and change to the following folder: C:\Program Files\Bosch\Digital Congress Network\Download and License Tool\Files Download the NCO with the next command line FTP with the command: <i>ftp -n -s:dcn-nco.txt x.x.x.x</i> Where x.x.x.x is the IP-address of the NCO Switch off the NCO and set the dipswitches all to off Switch on the NCO Start the Download and License Tool and start a NCO download. Switch off and on the CCU or NCO
NCO	download of NCO or CCU	
DCN-NCO DCN-CCU, INT-TX04/08/16/32	Unexpected behavior when adding powered system units to the optical ring	In case system units are added to the optical ring when the system is powered on, unexpected behavior can occur. Only connect units to the optical network when all units are powered off.
DCN NCO DCN-CCU INT-TX04/08/16/32	Audio disruption when switching on a transmitter	Select the option "enabled" in menu 4b (network mode).
DCN NCO DCN-CCU INT-TX04/08/16/32	Audio disruption when one of the CCUs is in the mode ""	Change the slave id "" to a number. (refer to menu 7I Multi Mode).

Product/function	Problem	Solution
INT-TX04/0816/32	The transmitter displays the message "No Network"	Connect a powered DCN Next Generation or DCN wireless system to the transmitter or select the option "standalone" in menu 4b (network mode)
INT-RX04/08/32	Charging indicator on the receiver is blinking	Check whether the receiver is still working correctly. If this is the case: the battery pack is fully charged and can be recharged after using it a while. If this is not the case: follow the instructions as given in the troubleshooting table.
DCN-CCU	DCN-CCU shows "Multi" while acting in "Single"	When changing from "single" to "multi" mode, the DCN-CCU can remain working in "single" mode. If this is the case follow next procedure: 1. Select "multi" on all connected CCUs 2. Switch off all CCUs. 3. Reset to defaults the NCO. 4. Switch on all CCUs.
DCN-CCU	Audio disruption during powering up/down a CCU in a Multi CCU system	During powering up/down a CCU in a Multi CCU system the audio on the delegate units, connected to the remaining CCU's, is shortly disrupted for 1 to 2 seconds.
DCN-CCU	Loss of settings after reboot of NCO in a Multi CCU system	In case the Network Controller (NCO) in a Multi CCU system is rebooted, the settings and configurations changed during the past 30 seconds can be lost. When configuring interpreter desks wait minimum 30 seconds before reboot the NCO.
LBB 4402/00 LBB 4404/00 PRS-4DEX4	Input routing does not work after download of optical devices	Change all inputs to CH00 and then to the required channel.
INT-TX	Transmitter does not work after updating firmware	Update FPGA to version 2.03 or higher Alternative solution: Update firmware of the INT-TX to version 2.80
DCN-IDENC	DCN-IDENC ID card encoder in not recognized in DCN-SW.	If other card readers/encoders are present or connected to the PC please disable them. Internal readers/encoders can be disabled in the BIOS or in the Windows Device Manager.
CNConfig	Error during installation "verify that you have access to the directory."	Ensure that you have the required administrator rights. Restart installation.